AW05W-6 WIRING DIAGRAM



CORD COLOR FULL NAME LIST:

SYMBOL	FULL NAME
PU	PURPLE
B	BLACK
Y	YELLOW
W	WHITE
R	RED
L	BLUE
G	GREEN
O	ORANGE
GR	GRAY
BR	BROWN
SB	SKY BLUE
Y/L	YELLOW/BLUE
B/R	BLACK/RED
B/Y	BLACK/YELLOW
G/Y	GREEN/YELLOW
Y/R	YELLOW/RED
Y/W	YELLOW/WHITE
L/Y	BLUE/YELLOW
LG	LIGHT GREEN
L/W	BLUE/WHITE
BR/W	BROWN/WHITE
G/B	GREEN/BLACK